

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

# APPARATUS FOR HEATING PLASTIC PIPES




ILLUSTRATION




DONALD PATTERSON  
APP# 10/764,146

Fig. 1




DONALD PATTERSON  
APP # 10/764,146

Fig. 1A



Donald PATTERSON  
APP # 10/764, 146  
Fig. 2



DONALD PATTERSON  
RPP# 10/764, 146  
FIG 3

